

Environmental Impact Statement

Volume II: Figures - Contents

Chapter 1 Introduction

No Figures

Chapter 2 Need for Alterations and Outline of Alternatives

No Figures

Chapter 3 Project Description

Figure 3.01	Permitted Work Currently Completed
Figure 3.02a	Phasing of Works
Figure 3.02b	Phasing of Works
Figure 3.03	Permitted Development Terminal Layout
Figure 3.04	(Typical Rubber Tyred Gantry Crane) *in chapter
Figure 3.05	Proposed Terminal Layout
Figure 3.06	Typical Straddle Carrier *in chapter
Figure 3.07	Typical Rail Mounted Gantry Crane *in chapter
Figure 3.08	Phase 1a Proposed Operational Layout
Figure 3.09	Comparison of container handling equipment *in chapter
Figure 3.10	Additional Terminal Operational Area
Figure 3.11	Comparison of Lighting – Permitted Development and Proposed
Figure 3.12	Lux Levels from Proposed High Mast Lighting
Figure 3.13	Permitted Development Quay Area Layout
Figure 3.14	Proposed Quay Layout
Figure 3.15	Comparison of Permitted Quay and Proposed Alterations
Figure 3.16	Quay Layout - Phase 1a and Phase 1b
Figure 3.17	Removal of Existing Dolphins
Figure 3.18	Location of Proposed Dolphins
Figure 3.19	Proposed Dolphins Elevations
Figure 3.20	Additional Dredging Layout
Figure 3.21	Permitted Development Building Locations
Figure 3.22	Proposed Building Locations
Figure 3.22a	Ground Floor Plan Custom Inspection Building
Figure 3.22b	Elevations Custom Inspection Building
Figure 3.23	Proposed Building Maintenance Layout
Figure 3.23a	Ground Floor Plan Terminal Office and Maintenance Building
Figure 3.23b	Elevations Terminal Office and Maintenance Building
Figure 3.23c	Contextual Elevations Terminal Office and Maintenance Building
Figure 3.23d	Contextual Elevations Terminal Office and Maintenance Building
Figure 3.24	Gantry Locations and Typical Section
Figure 3.25	Reefer Gantry Locations
Figure 3.26	Reefer Gantry Details
Figure 3.27	Interchange Area for Permitted Development and Proposed Alterations
Figure 3.28	Comparison of Red Line Boundaries

Chapter 4 Planning Policy

Figure 4.1 Ringaskiddy Planning Zonings

Chapter 5 Human Environment

- Figure 5.1 Aerial view of Shanbilly and Ringaskiddy, identifying the main existing industries and community receptors within the area. ***in chapter**
Figure 5.2 Illustrating the shipping lane, the location of the main sailing and rowing clubs; and sailing racing marks in the Lower Harbour ***in chapter**

Chapter 6 Cultural Heritage

- Figure 6.1 Summary Plan
Figure 6.2 Discovery Mapping of Ringaskiddy
Figure 6.3 Distribution of known Archaeological Sites
Figure 6.4 Extract from Down survey map of 1670
Figure 6.5 Extracts from Historic Maps of Cork Harbour
Figure 6.6 Extracts from OS Map First Edition
Figure 6.7 Map Showing Extent of Geophysical Survey
Figure 6.8 Map Showing Extent of Intertidal and Underwater Survey
Figure 6.9 Map Showing Depth Soundings
Figure 6.10 Images of Reclaimed Land in East Basin
Figure 6.11 Images of Intertidal Survey in West Basin
Figure 6.12 Images of Dive Area in East Basin
Figure 6.13 Underwater Dive Images
Figure 6.14 Extent of Underwater Survey
Figure 6.15 Images of Intertidal and Dive Survey

Chapter 7 Landscape and Visual

- Figure 7.1 Zone of Visual Influence
Figure 7.2 Landscape Character Area
Figure 7.3 Viewpoints Locations

Photomontages

Chapter 8 Traffic and Transport

- Figure 8.1 2015 Average 2-Way Flow – Carrs Hill, N28 ***in chapter**
Figure 8.2 Construction Traffic ***in chapter**
Figure 8.3 Construction Traffic Comparison ***in chapter**

Chapter 9 Noise and Vibration

- Figure 9.1 Noise Monitoring and Modelling Locations
Figure 9.2 Noise Monitoring and Modelling Locations
Figure 9.3 Noise Monitoring and Modelling Locations

Chapter 10 Air Quality and Climate

- Figure 10a Proposed Development Air Quality Zone ***in chapter**

Chapter 11 Soils and Geology

- Figure 11.1 Simplified Geology Map of Cork Harbour
Figure 11.2 Extract from GSI sheet 25
Figure 11.3 Geological Cross Section
Figure 11.4 Aquifer Classification

Chapter 12 Coastal Processes

- Figure 12.1 Flexible mesh tidal model of the Cork Estuary ***in chapter**
Figure 12.2 Extent of bathymetric data survey datasets ***in chapter**
Figure 12.3 Calibration locations for data presented ***in chapter**
Figure 12.4 Surface elevation for simulation period (CD) ***in chapter**
Figure 12.5 Tidal Elevation from Gauge and Model Data - Cobh Spring tide ***in chapter**
Figure 12.6 Tidal Elevation from Gauge and Model Data - Cobh Neap tide ***in chapter**
Figure 12.7 Tidal Elevation from Gauge and Model Data - Ringaskiddy Spring tide ***in chapter**

Figure 12.8	Tidal Elevation from Gauge and Model Data - Ringaskiddy Neap tide *in chapter
Figure 12.9	Baseline Bathymetry – Ringaskiddy *in chapter
Figure 12.10	Permitted development Current Regime Mid-ebb *in chapter
Figure 12.11	Permitted development Current Regime Mid-fld *in chapter
Figure 12.12	Permitted development Peak Ebb Current Speed *in chapter
Figure 12.13	Permitted development Peak Ebb Current Speed *in chapter
Figure 12.14	Vector Difference in Current Speed Mid-ebb (post minus pre-redevelopment) *in chapter
Figure 12.15	Vector Difference in Current Speed Mid-flood (post minus pre-redevelopment) *in chapter
Figure 12.16	Difference in Peak Current Speed Ebb- (post minus pre-redevelopment) *in chapter
Figure 12.17	Difference in Peak Current Speed Flood (post minus pre-redevelopment) *in chapter
Figure 12.18	Final Sedimentation following permitted development Dredging Operations *in chapter
Figure 12.19	Typical Mid-Ebb Suspended Sediment Concentration above Baseline during permitted development dredging *in chapter
Figure 12.20	Typical Mid-Flood Suspended Sediment Concentration above Baseline during permitted development dredging *in chapter
Figure 12.21	Average Suspended Sediment Concentration above Baseline during permitted development dredging *in chapter
Figure 12.22	Deposition Footprint for dumping of 385,000 m ³ of sediment from Oyster Bank and related area *in chapter
Figure 12.23	Maximum Concentration Contours (instantaneous) of suspended sediment averaged over the of water column dumping of 385,000 m ³ of sediment from Oyster Bank and related area *in chapter
Figure 12.24	Maximum Concentration (instantaneous) of suspended sediment in top 10 metres of water column dumping of 385,000 m ³ of sediment from Oyster Bank and related area *in chapter

Chapter 13 Water Environment

Figure 13.1	Location map showing Cork Harbour and nearby waterbodies *in chapter
Figure 13.2	Location map showing Western Celtic Sea and nearby Water Bodies *in chapter
Figure 13.3	Map Showing Designated Areas in Proximity to Cork Harbour *in chapter
Figure 13.4	WFD Status of Cork Harbour Study Area *in chapter
Figure 13.5	Sediment sample locations at Cork Harbour *in chapter
Figure 13.6	Extent of Irish tidal and storm surge model *in chapter
Figure 13.7	Location of Point where Water Levels were predicted *in chapter

Chapter 14 Marine Ecology

Figure 14.1.1	A close up of the proposed marine components of the alterations showing the lines for mean high water of spring tides (MHWS) and the corresponding low spring tide line (MLWS) *in chapter
Figure 14.1.2 A-D	A = top of rock armour revetment with narrow band of <i>Pelvetia</i> , <i>Fucus spiralis</i> and fine greens (<i>Enetromorpha</i> ?) B = base of revetment showing patchy <i>F. serratus</i> cover on loose boulders. C = close-up of dense <i>Ascophyllum</i> cover on main body of revetment; D = close-up of <i>F. serratus</i> on silted lower shore boulders *in chapter
Figure 14.1.3 A-D	A = Edible periwinkles and blue mussel – lower shore B = patch of the barnacle <i>Elminius modestus</i> , lower shore C = Green alga (<i>Ulva</i> sp.) Fine reds and <i>F. serratus</i> on extreme lower shore boulder. D = Fine reds and hydrozoa (?) on upper subtidal (shallow infralittoral) boulders, in very turbid waters at the base of the revetment. *in chapter
Figure 14.2.1	All species recorded in the vicinity of Cork Harbour *in chapter
Figure 14.2.2	Bottlenose dolphin sightings in the vicinity of Cork Harbour *in chapter
Figure 14.2.3	Common dolphin sightings recorded in the vicinity of Cork Harbour *in chapter
Figure 14.2.4	Fin whale sightings recorded in the vicinity of Cork Harbour *in chapter
Figure 14.2.5	Harbour porpoise sightings recorded in the vicinity of Cork Harbour *in chapter
Figure 14.2.6	Minke whale sightings recorded in the vicinity of Cork Harbour *in chapter
Figure 14.2.7	Unidentified cetacean species recorded in the vicinity of Cork Harbour *in chapter

Chapter 15 Terrestrial Ecology & Ornithology

Figure 15.1	Designated Sites for Nature Conservation
Figure 15.2	Habitat Survey Results

Chapter 16 Interactions

No Figures

Chapter 17 Summary of Submissions

No Figures